

CUST # 516 KEY COOPERATIVE UNIT # 66
1999 FREIGHTLINER CURR MILES 21,903.0
VIN # YHG50197

TECH / OP CODE DESCRIPTION

C86169 C 03 11/02/16 21,903.0

01 1 TRUCK TOWED IN.
01 3 FOUND AIR LEAK. REMOVED BOTH REAR CHAMBERS TO GET TO MOVE,
01 3 TRUCK WONT MOVE, FOUND POWER DIVIDER BAD AND REAR END
01 3 HOUSING DAMAGED. REMOVED THE POWER DIVIDER TO SEE IT IT WAS
01 3 DAMAGED. CUST DECIDED NOT TO REPAIR AT THIS TIME.

C82668 C 03 03/22/16 476,780.0

01 1 WIPERS DONT WORK
01 3 TEST WIPER SWITCH AND IT TESTED BAD. TESTED MOTOR AND THE
01 3 HIGH SIDE TESTED BAD. REPLACED SWITCH AND MOTOR.
02 1 NEEDS A CLUTCH ADJUSTMENT
02 3 ADJUSTED CLUTCH, REMOVED 1/4 FENDER AND LINKAGE WAS BENT CUT
02 3 OUT BENT PART AND ADJUSTED LINKAGE.

C80240 C 03 09/24/15 476,249.0

01 1 PARTS FOR RO #80081 THAT WERE NOT ADDED TO THE RO BY
01 1 MISTAKE. AIR HOSE WAS MADE FOR THE EMEGENCY VALVE THAT WAS
01 1 REPLACED

C80081 C 03 09/23/15 476,249.0

01 1 POWER STEERING PUMP OR LINES ARE LEAKING
01 3 FOUND JAM NUT LOOSE FOR SUPPLY LINE. TIGHTEN UP AND STILL
01 3 LEAKS. HAD TO REMOVE THE PUMP TO INSTALL NEW ORING. INSTALL
01 3 PUMP WITH NEW GASKET AND REPLACED SUCTION HOSE. FILLED WITH
01 3 OIL
02 1 CHECK OUT BATT. TROUBLE STARTING
02 3 LOAD TESTED BATT. REPLACE ALL 3 UNDER WARRANTY. WERE INSTALL
02 3 LAST YEAR
03 1 CHECK RAD FOR ANTIFREEZE FREEZE POING AND ADJ TO PROPER TEMP
03 1 IF NEEDED
03 3 TEMP WAS ONLY GOOD TO -10. DRAIN SOME COOLANT AND ADDED 100%
03 3 COOLANT.
04 1 DRIVER DOOR WONT STAY CLOSED AND HARD TO OPEN
04 3 REPLACE THE STRIKER LATCH AND LUBED UP PIVOT POINTS.
04 3 INSTALLED NEW CRANK
05 1 CLUTCH NEEDS ADJ
05 3 CHECKED OUT ANF FOUND ADJ FOR CLUTCH. AUTO ADJ CLUTCH
06 1 BRAKE PEDAL GOES TO THE FLOOR. IT IS AIR BRAKES
06 3 FOUND THE TREADLE VALVE AND EMERGENCY RELAY VALVE BAD.
06 3 REPLACED BOTH VALVES AND FITTINGS. ALL LINES, FITTINGS AND
06 3 VALVES ARE IN VERY BAD SHAPE DUE TO CORROSION.
07 1 CHECK AIR LINES TO AIR BAGS AND ALSO THE AIR BAGS THEMSELVES
07 3 BOTH FRONT AIR BAGS ON DRIVE AXLE ARE LEAKING AND ALSO NEEDS
07 3 TOP MOUNTS. REPLACED BOTH. ALL PARTS CAME APART VERY HARD
07 3 DUE TO CORROSION

C77361 C 03 04/07/15 475,873.0

01 1 ENGINE LIGHT IS ON

TECH / OP CODE DESCRIPTION

01 2 HOOK UP COMPUTER AND FOUND #1 INJECTOR BAD
01 3 REPLACE INJECTOR #1, ALSO FOUND CODE 0132 , ACCELERATOR
01 3 PEDAL VOLTAGE BELOW NORMAL- CLEAR CODE TEST DRIVE OK NOW
02 1 ADJUST BRAKES
03 1 ADJUST CLUTCH

C75287 C 03 12/02/14 475,398.0

01 1 CLUTCH ADJUSTED
01 3 FOUND TRANS CMAE LOOSE 1/2 BOLTS CAME OUT OF BELL HOUSING-
01 3 REPLACE 6 BOLTS AND TIGHTEN ALL OTHER, ADJUST INTERNAL AND
01 3 EXTERNAL ADJUSTMENT
02 1 HAVING PROBLEM WITH STARTER- STICKS
02 3 FOUND KEY SWITCH STICKING, BLOWER MOTOR ALSO STAYS ON WITH
02 3 KEY OFF. CHARGE BATTERIES, REPLACE IGNITION, SPLIT & CHECK
02 3 BATTERIES AND CONNECTIONS, CRANKS SLOW- LOAD TEST BATTERIES-
02 3 REPLACE BATTERIES, REMOVED STARTER AND FOUND FALLING APART
03 1 POWER STEERING LEAK
03 3 REPLACE RETURN LINE TO RESEVIOUR AND FILL IT. POWER WASH OFF
03 3 POWER STEERING SYSTEM AND RUN TO CHECK FOR LEAKS

C69407 C 03 11/26/13 468,425.0

01 1 AIR TANK LEAKING
01 3 REMOVE AIR TANK AND STRAPS PLUG OFF LINE
02 1 2 SPEED GASKET IS LEAKING
02 2 FOUND PINION SEAL LEAKING
02 3 REPLACE SEAL AND TIGHTEN UP 2 MOUNTING NUTS
03 1 ADJUST BRAKE
03 2 FRONT SLACK ADJUSTERS ARE FROZE UP
03 3 REPLACE SLACK ADJUSTERS
04 1 REPLACE FUEL FILTER
05 1 PARTS PICK UP BY DRIVER

C58647 C 03 03/14/12 460,318.0

01 11 1 ADJUST CLUTCH

C55931 C 03 10/12/11 456,296.0

01 1 CHECK ALTERNATOR
01 1 AND LOAD TEST BATTERIES
01 3 ALT- 14.3
01 3 BATTERIES ARE GOOD

C52822 C 03 04/11/11 21,669.0

01 04 1 REPLACE EMERGENCY BRAKE VALVE

C46630 C 03 04/20/10 448,478.0

01 1 OIL LEAK
01 2 FOUND VALVE COVER GASKET PINCHED ON BACK OF ENGINE
01 3 TOOK VALVE COVER OFF REALIGNED GASKET- REINSTALL VALVE
01 3 COVER AND CHECK FOR LEAKS
02 04 1 AIR LEAK ON TOP OF DRIVE AXLE

RUN: 10/06/2017 9:29 SERVICE UNIT HISTORY BY UNIT
00/00/00 - 99/99/99 QS - MARSHALLTOWN

PAGE 3

TECH / OP CODE DESCRIPTION

02 3 CHECK FOR LEAKS WITH BRAKES APPLIED AND RELEASED, ALSO
02 3 CHECKED CHAMBERS, NO LEAKS WERE FOUND, ADJUST ALL BRAKES

C46650 C 03 04/17/10 448,351.0
01 1 REPLACE #4 INJECTOR

C46346 C 03 04/17/10 448,351.0
01 12 1 USES ALOT OF OIL
01 3 FOUND ENGINE IS BAD
02 12 1 R & I ENGINE
02 1 REPLACE ROCKER BOX GASKETS,AC BELT, INJ ORINGS
03 12 1 RUN OVER HEAD AND ADJUST VALVES AND INJECTORS